

Hamer Fire District RedZone statistics created 8/7/2008 4:49:55 PM
6 total records

Is structure address clearly visible from street?

- 50.0% (3) - present, not visible
- 50.0% (3) - not present
- 0.0% (0) - <Not Answered>
- 0.0% (0) - present and visible

Is there more than one access/egress?

- 83.3% (5) - one way access
- 16.7% (1) - more than one way access
- 0.0% (0) - <Not Answered>

Width of driveway

- 66.7% (4) - 20-26 ft
- 16.7% (1) - 20 ft or less
- 16.7% (1) - > 26 ft
- 0.0% (0) - <Not Answered>
- 0.0% (0) - inaccessible

What is the length of the driveway in feet?

- 50.0% (3) - less than 150 ft
- 33.3% (2) - greater than 1000 ft
- 16.7% (1) - 150 to 1000 ft
- 0.0% (0) - <Not Answered>

Is there vertical clearance?

- 100.0% (6) - yes
- 0.0% (0) - <Not Answered>
- 0.0% (0) - no

Is there horizontal clearance?

- 100.0% (6) - yes
- 0.0% (0) - <Not Answered>
- 0.0% (0) - no

Is access to the home gated?

- 100.0% (6) - no
- 0.0% (0) - <Not Answered>
- 0.0% (0) - yes, siren activated
- 0.0% (0) - yes, not siren activated

Grade of driveway:

- 100.0% (6) - flat (0% - 5%)
- 0.0% (0) - <Not Answered>
- 0.0% (0) - low (6% - 8%)
- 0.0% (0) - moderate (9% - 12%)
- 0.0% (0) - steep (> 12%)

Is there an adequate fire dept turnaround?

- 100.0% (6) - yes
- 0.0% (0) - <Not Answered>
- 0.0% (0) - no

Bridges accessing the property

- 83.3% (5) - not present
- 16.7% (1) - present and unrated / substandard
- 0.0% (0) - <Not Answered>
- 0.0% (0) - present and rated (>20,000 axle load)

Describe the parking.

- 100.0% (6) - room for two or more rigs
- 0.0% (0) - <Not Answered>
- 0.0% (0) - room for 1 rig
- 0.0% (0) - no room for rigs without lane blockage

Placement of gas and electric utilities

- 50.0% (3) - above ground propane tank, underground power
- 33.3% (2) - above ground propane tank and power
- 16.7% (1) - underground gas and power
- 0.0% (0) - <Not Answered>
- 0.0% (0) - underground gas, overhead power
- 0.0% (0) - none

If present, does propane tank have >3m fuel-free buffer from vegetation/fuels?

- 66.7% (4) - yes
- 16.7% (1) - no
- 16.7% (1) - not applicable
- 0.0% (0) - <Not Answered>

Natural gas/propane shutoff

- 33.3% (2) - east
- 33.3% (2) - unknown
- 16.7% (1) - north
- 16.7% (1) - not applicable
- 0.0% (0) - <Not Answered>
- 0.0% (0) - south
- 0.0% (0) - west

Electrical shutoff

- 33.3% (2) - east
- 33.3% (2) - unknown
- 16.7% (1) - north
- 16.7% (1) - south
- 0.0% (0) - <Not Answered>
- 0.0% (0) - west

What is the predominant aspect around the structure?

- 100.0% (6) - flat (0-5%)
- 0.0% (0) - <Not Answered>
- 0.0% (0) - north (nw<-n->ne)
- 0.0% (0) - east (ne<-e->se)
- 0.0% (0) - south (se<-s->sw)
- 0.0% (0) - west (sw<-w->nw)

Overall slope of the area within 150 ft of structure

- 100.0% (6) - less than 9%
- 0.0% (0) - <Not Answered>
- 0.0% (0) - between 10% and 20%
- 0.0% (0) - between 21% and 30%
- 0.0% (0) - between 31% and 40%
- 0.0% (0) - greater than 41%

What is the fuel load around the structure?

- 66.7% (4) - moderate
- 33.3% (2) - light
- 0.0% (0) - <Not Answered>
- 0.0% (0) - heavy

What is the fuel type?

(Multiple Answer)

- 100.0% (6) - grass
- 50.0% (3) - timber
- 33.3% (2) - brush
- 16.7% (1) - ground fuels
- 0.0% (0) - <Not Answered>
- 0.0% (0) - debris

Describe ladder fuels

- 50.0% (3) - ladder fuels within 30 ft of structure
- 33.3% (2) - none
- 16.7% (1) - ladder fuels within 75 ft of structure
- 0.0% (0) - <Not Answered>
- 0.0% (0) - ladder fuels within 150 ft of structure

Defensible space

- 50.0% (3) - 50-75 feet
- 33.3% (2) - more than 75 feet
- 16.7% (1) - 30-50 feet
- 0.0% (0) - <Not Answered>
- 0.0% (0) - less than 30 feet or none

Describe the defensible space

- 66.7% (4) - non-conforming
- 33.3% (2) - conforming
- 0.0% (0) - <Not Answered>
- 0.0% (0) - none

Vegetation near roof

(Multiple Answer)

- 33.3% (2) - not applicable
- 33.3% (2) - branches/limbs within 5 feet
- 16.7% (1) - <Not Answered>
- 16.7% (1) - overhanging branches/limbs
- 0.0% (0) - leaf and/or needles on roof/gutters

Describe the fuels in the defensible space.

- 66.7% (4) - irrigated
- 33.3% (2) - not irrigated
- 0.0% (0) - <Not Answered>
- 0.0% (0) - no fuels

Number of stories

(Multiple Answer)

- 83.3% (5) - 1
- 16.7% (1) - 2
- 0.0% (0) - <Not Answered>
- 0.0% (0) - 3+
- 0.0% (0) - basement

What type of roofing material?

- 66.7% (4) - metal
- 16.7% (1) - asphalt
- 16.7% (1) - wood
- 0.0% (0) - <Not Answered>
- 0.0% (0) - tile
- 0.0% (0) - other

What is the siding material?

- 50.0% (3) - combustible or vinyl siding
- 33.3% (2) - non-combustible stucco or metal siding
- 16.7% (1) - highly combustible non treated wood shakes/siding
- 0.0% (0) - <Not Answered>

Eaves

- 50.0% (3) - enclosed
- 33.3% (2) - not enclosed
- 16.7% (1) - not present
- 0.0% (0) - <Not Answered>

Balcony, decks, or porches

100.0% (6) - none or fire resistant material, sheathed-in

0.0% (0) - <Not Answered>

0.0% (0) - combustible material, sheathed-in

0.0% (0) - combustible material, not sheathed-in

Describe the type of occupancy

83.3% (5) - primary residence

16.7% (1) - seasonal residence

0.0% (0) - <Not Answered>

0.0% (0) - outbuilding

0.0% (0) - cabin

0.0% (0) - lodge/hotel/camp

0.0% (0) - agriculture

0.0% (0) - commercial facility

0.0% (0) - campground

0.0% (0) - infrastructure facility

0.0% (0) - other

Number of similar structures on this site

100.0% (6) - 1

0.0% (0) - <Not Answered>

0.0% (0) - 2

0.0% (0) - 3

0.0% (0) - 4+

Describe the known hazards

(Multiple Answer)

50.0% (3) - propane tanks

33.3% (2) - other

16.7% (1) - poor escape routes/safety zones

16.7% (1) - overhead electrical line hazard

0.0% (0) - <Not Answered>

0.0% (0) - dangerous animals

0.0% (0) - livestock

0.0% (0) - hazmat

0.0% (0) - above ground fuel storage

Evacuation concerns

(Multiple Answer)

100.0% (6) - other

0.0% (0) - <Not Answered>

0.0% (0) - handicapped

0.0% (0) - elderly

0.0% (0) - children

0.0% (0) - insufficient resident transport

0.0% (0) - difficult access

0.0% (0) - large numbers of livestock

Specific items the homeowner can mitigate?

(Multiple Answer)

- 66.7% (4) - post visible address marker
- 66.7% (4) - cut back vegetation along driveway
- 50.0% (3) - mow/rake near home
- 33.3% (2) - limb trees to 6 feet
- 0.0% (0) - <Not Answered>
- 0.0% (0) - clean under deck
- 0.0% (0) - skirt deck and openings
- 0.0% (0) - clean under home
- 0.0% (0) - clean roof and gutters
- 0.0% (0) - improve driveway or access road
- 0.0% (0) - general cleanup of property
- 0.0% (0) - relocate vehicles away from home
- 0.0% (0) - clear around propane tank
- 0.0% (0) - move firewood away from home
- 0.0% (0) - other

Did you have contact the homeowner during your survey?

- 83.3% (5) - no
- 16.7% (1) - yes
- 0.0% (0) - <Not Answered>